

# FAW Audi Q3

2021

VIN | Lfv2B2F30M7727953



GENERATED  
Mar 4, 2026



FUEL TYPE  
Gasoline



VIN  
Lfv2B2F30M7727953



REPORT ID  
#f8775b5ee0f9

## Overall Evaluation

Vehicle risk assessment and purchase recommendation

### VEHICLE CONDITION

# Excellent Condition

Approved for Import

Vehicle exhibits strong structural integrity with only minor collision repairs and has been conscientiously maintained throughout its service life.

### KEY FINDINGS

6

- Two minor collisions resulted in front and rear frame repairs



*Based on: Accident and damage history shows two minor collision events affecting the front and rear frames*

- Low compensation ratios and no major accidents



*Based on: Insurance records indicate a maximum single-claim compensation ratio of 3% and no fire, water, or theft incidents*

- Body condition graded A with a score of 90



Based on: Structural inspection reveals an overall body condition rating of A (90) with only minor repairs on front and rear frames

- Comprehensive maintenance with 22 service events ✓

Based on: Service history includes routine oil/filter changes, tire replacements, software updates, and formal inspections over 56 months

- Consistent mileage progression with no anomalies ✓

Based on: Mileage readings increase steadily from delivery at 10 km to 44,637 km with all readings verified

- No recall or warranty work recorded ✓

Based on: Service records show no warranty claims or recall repairs were required



### RECOMMENDATION

✓ **Approved for Import**

Given its excellent structural rating, minor repair history, and thorough maintenance, this vehicle is suitable for import.

## Vehicle Identity

Complete specifications and identification details

### 2021 FAW Audi Q3 1.4T Dual-Clutch Transmission Entry Elegant Edition (FV7145LADCG)

BRAND

**Audi**

SERIES

**FAW Audi Q3**

YEAR

**2021**

MANUFACTURER

**FAW Audi**

VIN **LFV2B2F30M7727953**



### Engine

Displacement

**1.4T**

Engine Model

**DJS**

Fuel Type

**Gasoline**

Fuel Grade  
**97 RON (Beijing 95 RON)**

Emission Standard  
**China VI**



## Transmission

Gearbox  
**Dual-Clutch Transmission**

Drive Type  
**Front Engine Front-Wheel Drive**



## Dimensions

Wheelbase  
**2680 mm**



## Weight & Capacity

Seats  
**5**

Doors  
**Five-Door**



## Classification

Vehicle Class  
**SUV**



## Market Information

MSRP  
**¥274300.0**

Market Date  
**202009**

## Vehicle Title

Title status assessment and implications

Clean



## Clean Title

This vehicle has only minor collision repairs to the front and rear frames, with low claim payouts and no major accidents, fire, flood, or total-loss events. Continuous insurance coverage and good structural integrity confirm it is roadworthy with no significant damage history.

### KEY FACTORS

- 1 Minor collision history**   
*Based on: Two minor collisions affecting the front and rear frames were recorded, each with low compensation ratios*
- 2 No major structural damage**   
*Based on: Inspection shows all other components are in normal condition with minor frame repairs only*
- 3 No total-loss or severe incidents**   
*Based on: There are no records of fire, flood, theft, or insurer-declared total loss in the vehicle history*
- 4 Continuous insurance coverage**   
*Based on: Commercial and compulsory insurance remained uninterrupted throughout the vehicle's service life*



#### Financing

Clean title supports standard financing options.



#### Insurance

No title issues affecting insurance coverage.



#### Resale Value

Clean history supports strong resale value.

## Body Appearance Checklist

Detailed inspection results for all body panels

GRADE

**A**

 NORMAL

**9** / 11

 MINOR

**2** / 11

 MAJOR

**0** / 11



### Very Good

Minor damage on front and rear frames, otherwise structure intact

### Shield Detailed Panel Status

Front Frame	! Minor Repair	Minor damage reported
Rear Frame	! Minor Repair	Minor damage reported
Roof Structure	✓ Normal	No damage detected
Undercarriage	✓ Normal	No damage detected
Front Left Panel	✓ Normal	No damage detected
Rear Left Panel	✓ Normal	No damage detected
Middle Left Panel	✓ Normal	No damage detected
Front Right Panel	✓ Normal	No damage detected
Rear Right Panel	✓ Normal	No damage detected

Middle Right Panel ✓ Normal

No damage detected

Interior ✓ Normal

No damage detected

## Accident & Damage Records

Reported collision and damage history

⚠️ 2 Records

### 1 Collision • Minor



Affected Area

Front Frame



Data Source

Insurance Records



Type

Collision

Minor collision resulting in frame damage

### 2 Collision • Minor



Affected Area

Rear Frame



Data Source

Insurance Records



Type

Collision

Minor collision resulting in frame damage



2 minor collisions recorded, no major incidents

## Mileage Verification Timeline

Complete odometer reading history from registration and service records




CURRENT MILEAGE

**44,637** km



ODOMETER TREND

— Mileage (km)



**44,627**  
km / year  
AVG ANNUAL

**20**  
entries  
TOTAL RECORDS

**Jun 2021**  
10 km  
FIRST RECORD

**Aug 2025**  
44,637 km  
LATEST RECORD

ALL RECORDS

DATE	MILEAGE	SOURCE	STATUS
Jun 2021	<b>10 km</b>	Registration	✓ Verified
Jun 2021	<b>20 km</b> +10	Inspection	✓ Verified
Nov 2021	<b>1,214 km</b> +1,194	Service Record	✓ Verified
Jan 2022	<b>4,550 km</b> +3,336	Service Record	✓ Verified
Mar 2022	<b>6,378 km</b> +1,828	Service Record	✓ Verified

DATE	MILEAGE	SOURCE	STATUS
May 2022	<b>6,993 km</b> +615	Service Record	 <b>Verified</b>
DATE	MILEAGE	SOURCE	STATUS
Jul 2022	<b>8,038 km</b> +1,045	Service Record	 <b>Verified</b>
DATE	MILEAGE	SOURCE	STATUS
Dec 2022	<b>9,041 km</b> +1,003	Service Record	 <b>Verified</b>
DATE	MILEAGE	SOURCE	STATUS
Feb 2023	<b>13,135 km</b> +4,094	Service Record	 <b>Verified</b>
DATE	MILEAGE	SOURCE	STATUS
Mar 2023	<b>13,420 km</b> +285	Service Record	 <b>Verified</b>
DATE	MILEAGE	SOURCE	STATUS
Mar 2023	<b>13,554 km</b> +134	Service Record	 <b>Verified</b>
DATE	MILEAGE	SOURCE	STATUS
Oct 2023	<b>18,079 km</b> +4,525	Service Record	 <b>Verified</b>
DATE	MILEAGE	SOURCE	STATUS
Nov 2023	<b>19,012 km</b> +933	Service Record	 <b>Verified</b>
DATE	MILEAGE	SOURCE	STATUS
Mar 2024	<b>22,418 km</b> +3,406	Service Record	 <b>Verified</b>
DATE	MILEAGE	SOURCE	STATUS
Apr 2024	<b>26,190 km</b> +3,772	Service Record	 <b>Verified</b>
DATE	MILEAGE	SOURCE	STATUS
Aug 2024	<b>30,025 km</b> +3,835	Service Record	 <b>Verified</b>
DATE	MILEAGE	SOURCE	STATUS
Oct 2024	<b>34,715 km</b> +4,690	Service Record	 <b>Verified</b>
DATE	MILEAGE	SOURCE	STATUS
Nov 2024	<b>35,333 km</b> +618	Service Record	 <b>Verified</b>
DATE	MILEAGE	SOURCE	STATUS

Jun 2025

43,017 km +7,684

Service Record

✓ Verified

DATE

MILEAGE

SOURCE

STATUS

Aug 2025

44,637 km +1,620

Service Record

✓ Verified



### Odometer Verified

Mileage Verified - No Anomalies Detected



## Maintenance Record Summary

22 Records

Complete service history with detailed maintenance records and parts replacement



LAST SERVICE

Aug 2025

Most recent service visit



OIL CHANGES

6 services

Oil & lubrication services



PARTS REPLACED

12 services

Service visits with parts work



## Maintenance History Timeline

Chronological record of all services



Aug 2025

✓ LATEST

Maintenance

↻ 44,637 km

Routine maintenance, oil change; air filter, throttle control unit cleaning and cabin dust/pollen filter installation.



PARTS & WORK



Oil filter



air filter



pollen filter

- ✓ washer fluid 1.5 L
- ✓ engine oil 0W-20 4 L
- ✓ A/C purifier



 **Jun 2025**

**Repair**

 43,017 km

Throttle body cleaning; staff tire change.

 **PARTS & WORK**

- ✓ Throttle valve cleaner



 **Nov 2024**

**Repair**

 35,333 km

Tire replacement.



 **Oct 2024**

**Maintenance**

 34,715 km

Routine maintenance and oil change.

 **PARTS & WORK**

- ✓ Oil filter
- ✓ engine oil 0W-20 4 L



 **Aug 2024**

**Repair**

 30,025 km

Snow tire replacement.



 **Apr 2024**

**Maintenance**

 26,190 km

Oil change; air filter, spark plug, dust and pollen filter removal and installation.

 **PARTS & WORK**

-  Oil filter
-  air filter
-  spark plug
-  pollen filter
-  cover panel
-  engine oil 0W-20 4 L
-  A/C purifier



 **Mar 2024**

**Repair**

 22,418 km

Tire replacement.



 **Dec 2023**

**Repair**

 19,012 km

Tire replacement; store tires for one year.



 **Nov 2023**

**Repair**

↻ 18,079 km

Windshield washer fluid service.

 PARTS & WORK

-  Windshield washer fluid 1.5 L concentrate
-  mixed fluid



 **Oct 2023**

Maintenance

↻ 18,079 km

Routine maintenance and oil change.

 PARTS & WORK

-  Filter
-  engine oil 0W-20 4 L



 **Mar 2023**

Repair

↻ 13,135 km

Cabin dust and pollen filter removal and installation.

 PARTS & WORK

-  Pollen filter



 **Mar 2023**

Maintenance

↻ 13,420 km

Routine maintenance and oil change; air filter element removal and installation.

 PARTS & WORK

- ✓ Filter
- ✓ air filter
- ✓ engine oil 0W-20 4 L
- ✓ A/C professional purifier



 **Mar 2023**

**Repair**

 13,554 km

Tire replacement.



 **Feb 2023**

**Service**

 13,135 km

Convenient steering times increased from 3 to 5.



 **Dec 2022**

**Repair**

 9,041 km

 **PARTS & WORK**

- ✓ Windshield washer fluid 1.5 L concentrate



 **Jul 2022**

**Insurance Service**

 8,038 km

Vent panel removal and installation.

 **PARTS & WORK**

- ✓ Sealant kit
- ✓ windshield glass kit
- ✓ windshield



**May 2022**

**Market Service**

6,993 km

Software update; battery registration.



**Mar 2022**

**Maintenance**

6,378 km

First service for Q3 1.4.

**PARTS & WORK**

- ✓ Filter
- ✓ engine oil OW-20 4 L



**Jan 2022**

**Repair**

4,550 km

Battery removal and installation.

**PARTS & WORK**

- ✓ Battery



**Nov 2021**

**Repair**

1,214 km

Tire replacement; store tires for one year.



**Jun 2021**

**Inspection**

10 km

Vehicle delivery inspection.



**Jun 2021**

**PDI**

20 km

Vehicle delivery inspection.

## Insurance Claims

Vehicle insurance claim history

3 Claims



**2**

COMMERCIAL



**1**

COMPULSORY



**Property Damage**

COMMERCIAL

Settled



Reference  
**Claim #1**



Damage  
**Body Damage**



Provider  
**Commercial Insurance**

Claim for frame repair



**Property Damage**

COMMERCIAL

Settled



Reference  
**Claim #2**



Damage  
**Body Damage**



Provider  
**Commercial Insurance**

Claim for rear frame repair



**Liability**  
COMPULSORY

● Settled



Reference  
**Claim #3**



Damage  
**Liability**



Provider  
**Compulsory Insurance**

Compulsory insurance liability claim



3 claims filed: 2 commercial and 1 compulsory



## Report Disclaimer & Trust Signals

This vehicle history report is compiled from multiple trusted data sources to provide you with comprehensive information about this vehicle's past.

### DATA SOURCES



State DMV Records



Insurance Companies



Service Centers



Auto Auctions



Collision Repair Facilities



Fire & Police  
Departments



### IMPORTANT NOTICE

This report is provided for informational purposes only. While we strive for accuracy, China Vehicle History does not guarantee the completeness or accuracy of the information contained herein. This report should be used as one of several tools in evaluating a vehicle purchase. We recommend a professional mechanical inspection before any vehicle purchase.